

## Daily Status Report From Emcs For Wurzel Ltd

**This report provides IMPORTANT information on your sites.**

Please contact the providers Technical Support Department if any Radio fails / Polling issues are not restored so that it can be investigated.

**\* \* Do Not Disregard \* \***

**Total Commissioned Sites: 18**

**5 alarm activations were logged for your sites between 6 AM yesterday and 6 AM today. See your daily activations report for full details.**

***None of your sites had policed alarms in the same period.***

***This Daily Status Report will Display Details of :***

1. Sites currently in Line Fault (4)
2. Sites with a path enablement date yesterday (0)
3. Sites that had their first signal logged yesterday (0)
4. Sites commissioned yesterday (0).
5. Sites decommissioned yesterday (0).

### Line Faults - Oldest First

PLEASE NOTE: Sites fitted with CSL DualCOM and RedCARE GSM are capable of having two distinct line faults - a Land Line Fault and a GID fault.

Only when both of these are in Line Fault will the whole System be in line fault. For your information, this report will show the status of the Land Line and the GID even if only one is in Line Fault.

|              |               |           |
|--------------|---------------|-----------|
| Contract No. | Customer Name | User Ref. |
| 41001951     | Worths Garage |           |

Trans: 1    Texecom Smartcom / Pro IP/4G02400001951

**Full Comms Failure Since: 02/04/2025 at 12:37:51**

**41002318                      6 Morton Way, Halstead**

Trans: 1    Texecom Smartcom / Pro IP/4G02400002318

**Full Comms Failure Since: 23/04/2025 at 09:41:25**

**88020722                      Compton Wynyates Estate**

Trans: 1      Dahua      904020722      Ref. emcs

**Landline Comms in Fault Since 08/09/2026 at 05:20:31**

**Full Comms Failure Since: 08/09/2026 at 05:32:46**

**41000351                      Compton Wynyates - Machinery Barn**

Trans: 1      Texecom Smartcom / Pro IP SP02400000351

**Full Comms Failure Since: 08/09/2026 at 21:00:34**

IP Comms Failure Since: 08/09/2026 at 21:00:34