

Daily New Record Report Wurzel Ltd

Summary of Records Selected

Sites Monitored by Wurzel Ltd

Dahua

88020722

Compton Wynyates Estate

Tx No. 1

Panel ID: 20722

Commissioned

Compton Wynyates Estate
Compton Wynyates
Warwick
CV35 0UD

88020722
Phone: 01295680229

SITE COMMENT: 4 PTZ 8 Statics 23/03/2026 JOH
Installer: Wurzel Ltd

Site Commissioned on 23/03/2026

Confirmation Required For Intruders: No
Password: ELVIS
Default Remote Reset Type: None

Confirmation Required For PAs: No
Duress Code: None

AREAS

Number/Description: **1 VSS Transmitter**
O/C Mon Type:
Last O/C Signal Recd: 23/03/2026 20:00:13

Schedule No.1: Open/Close (Type: Schedules)							
	<i>Mon</i>	<i>Tue</i>	<i>Wed</i>	<i>Thu</i>	<i>Fri</i>	<i>Sat</i>	<i>Sun</i>
Open	07:00	07:00	07:00	07:00	07:00	06:00	06:00
Close	20:00	20:00	20:00	20:00	23:00	23:00	23:00

No Active Temporary Schedules

No URNs available for this site

Available Site and Agency Action Contacts. See Sections below for other action types.

Site Actions
Group.1 MAIN SITE 01295680229

Installer
Group.1 Wurzel Ltd

Key Holder Details

Key Holder Group No: 1

Main Key Holder Group

John Blaikie (House Manager) (1)

Cancel Alarms: YES Change Data: YES Change Times: YES Change KH: YES Call List: YES

NOTES:

Normally Available

- 1 Landline 01295680761
- 2 Mobile 07572006864

Jonathan Simpson (Maintenance Manager) (2)

Cancel Alarms: YES Change Data: YES Change Times: YES Change KH: YES Call List: YES

NOTES:

Normally Available

- 1 Landline 01295680698
- 2 Mobile 07827275202

Cherilyn Caple (Housekeeper) (3)

Cancel Alarms: YES Change Data: YES Change Times: NO Change KH: NO Call List: YES

NOTES:

Normally Available

- 1 Landline 01608663378
- 2 Mobile 07866820881

Spencer Northampton (Owner) (4)

Cancel Alarms: YES Change Data: YES Change Times: YES Change KH: YES Call List: YES

NOTES:

Normally Available

- 1 Landline 01295680229
- 2 Mobile 07811123687

Key Holder Group No: 2

VSS Faults

Installer (1)

Cancel Alarms: YES Change Data: YES Change Times: YES Change KH: YES Call List: YES

support@wurzels.co.uk

NOTES:

Normally Available

Key Holder Group No: 3

IT Support

support@emcs.co.uk (1)

Cancel Alarms: YES Change Data: YES Change Times: YES Change KH: YES Call List: YES

support@emcs.co.uk

NOTES:

Normally Available

Key Holder Group No: 4

Commissioning Completed

cherie.oconnor@emcs.co.uk (1)

Cancel Alarms: YES Change Data: YES Change Times: YES Change KH: YES Call List: YES

cherie.oconnor@emcs.co.uk

Normally Available

Key Holder Group No: 5


False Alarm Support Team Review

FAST (1)

Cancel Alarms: YES Change Data: YES Change Times: YES Change KH: YES Call List: YES

fast@emcs.co.uk

Normally Available



Alarm Programming

Row	Event	Set Actions	Unset Actions	Method	Linked URN:
3	Low Battery	KE2	KE2	Automated Email	
	Strategy:Wait Until Contact Becomes Available: - used for 1 action				
4	VSS Picture received	NO3SO1KO1KT1	NO3SO1KO1KT1	Automated SMS/Operator	
	Strategy:Wait Until Contact Becomes Available: - used for 1 action				
5	Video Loss	KE2	KE2	Automated Email	
	Strategy:Wait Until Contact Becomes Available: - used for 1 action				
13	Data Transmit Fail	KE2	KE2	Automated Email	
	Strategy:Wait Until Contact Becomes Available: - used for 1 action				
14	VSS Zone Isolated	KE2	KE2	Automated Email	
	Strategy:Wait Until Contact Becomes Available: - used for 1 action				
15	DVR Disc Full	KE2	KE2	Automated Email	
	Strategy:Wait Until Contact Becomes Available: - used for 1 action				
16	DVR Disc Error	KE2	KE2	Automated Email	
17	Excessive Zone Isolated	KE2	KE2	Automated Email	
	Strategy:Wait Until Contact Becomes Available: - used for 1 action				
18	VSS Connection Failure	NO3SO1KO1KT1	NO3SO1KO1KT1	Automated SMS/Operator	
	Strategy:Wait Until Contact Becomes Available: - used for 1 action				
19	Perimeter Alert	NO3	NO3	Operator	
20	Perimeter Intruder	NO3SO1KO1KT1	NO3SO1KO1KT1	Automated SMS/Operator	
	Strategy:Wait Until Contact Becomes Available: - used for 1 action				
21	Excessive Zone Reinstated	KE2	KE2	Automated Email	
	Strategy:Wait Until Contact Becomes Available: - used for 1 action				
22	Line Crossed	NO3SO1KO1KT1	NO3SO1KO1KT1	Automated SMS/Operator	
	Strategy:Wait Until Contact Becomes Available: - used for 1 action				
25	DVR Event Queue Cleared	KE2	KE2	Automated Email	
	Strategy:Wait Until Contact Becomes Available: - used for 1 action				
26	DVR Double Recording Data	KE2	KE2	Automated Email	
	Strategy:Wait Until Contact Becomes Available: - used for 1 action				
27	DVR Double Recording	KE2	KE2	Automated Email	
	Strategy:Wait Until Contact Becomes Available: - used for 1 action				
28	DVR Recording Stopped	KE2	KE2	Automated Email	
	Strategy:Wait Until Contact Becomes Available: - used for 1 action				
30	Decommissioning alarm	KE3	KE3	Automated Email	
	Strategy:Wait Until Contact Becomes Available: - used for 1 action				
31	Video Motion Alarm	NO3SO1KO1KT1	NO3SO1KO1KT1	Automated SMS/Operator	
	Strategy:Wait Until Contact Becomes Available: - used for 1 action				
32	Video Analytics	NO3SO1KO1KT1	NO3SO1KO1KT1	Automated SMS/Operator	
	Strategy:Wait Until Contact Becomes Available: - used for 1 action				
33	Person Detected	NO3SO1KO1KT1	NO3SO1KO1KT1	Automated SMS/Operator	
	Strategy:Wait Until Contact Becomes Available: - used for 1 action				
34	Vehicle Detected	NO3SO1KO1KT1	NO3SO1KO1KT1	Automated SMS/Operator	
	Strategy:Wait Until Contact Becomes Available: - used for 1 action				
35	Face Detected	NO3SO1KO1KT1	NO3SO1KO1KT1	Automated SMS/Operator	
	Strategy:Wait Until Contact Becomes Available: - used for 1 action				
38	Tamper Alarm	KV1KT1	KV1KT1	Automated SMS/Automated Voice	
	Strategy:More than one strategy used for 2 actions				
39	Area Entered	NO3SO1KO1KT1	NO3SO1KO1KT1	Automated SMS/Operator	
	Strategy:Wait Until Contact Becomes Available: - used for 1 action				
40	Auto Command Failed	KE2	KE2	Automated Email	
	Strategy:Wait Until Contact Becomes Available: - used for 1 action				
41	VSS Audio Challenge	CC1	CC1	Automated Command	
42	Commisioning Complete	KE4	KE4	Automated Email	
	Strategy:Wait Until Contact Becomes Available: - used for 1 action				

43	Scheduling Amendment	KE5	KE5	Automated Email
	Strategy:Wait Until Contact Becomes Available: - used for 1 action			
44	Masking Review	KE5	KE5	Automated Email
	Strategy:Wait Until Contact Becomes Available: - used for 1 action			
45	VV/Wireless Connection Charge	KE4	KE4	Automated Email
	Strategy:Wait Until Contact Becomes Available: - used for 1 action			
46	Standard VSS Connection Charge	KE4	KE4	Automated Email
	Strategy:Wait Until Contact Becomes Available: - used for 1 action			
47	Weekend VSS Connection Charge	KE4	KE4	Automated Email
	Strategy:Wait Until Contact Becomes Available: - used for 1 action			
48	W/e Wireless Connection Charge	KE4	KE4	Automated Email
	Strategy:Wait Until Contact Becomes Available: - used for 1 action			
49	VSS Trial Passed	RA1	RA1	Automated Report
50	VSS Trial Failed	RA2	RA2	Automated Report
51	Multiple Camera Failure	KT1KE2	KT1KE2	Automated Email/Automated SMS
	Strategy:Wait Until Contact Becomes Available: - used for 2 action			
52	Loitering	NO3SO1KO1KT1	NO3SO1KO1KT1	Automated SMS/Operator
	Strategy:Wait Until Contact Becomes Available: - used for 1 action			
53	Open	CC3	CC3	Automated Command
54	Close	CC2	CC2	Automated Command
55	VSS Tamper	KT1KE2	KT1KE2	Automated Email/Automated SMS
	Strategy:Wait Until Contact Becomes Available: - used for 2 action			
Actions				
	<i>A</i>	<i>Special instructions</i>	<i>G</i>	<i>General Agency</i>
	<i>M</i>	<i>Medical Agency</i>	<i>R</i>	<i>Report</i>
Key	<i>C</i>	<i>Reverse Chanel Command</i>	<i>I</i>	<i>Installer</i>
	<i>N</i>	<i>Information Page</i>	<i>S</i>	<i>Site</i>
	<i>F</i>	<i>Fire Service</i>	<i>K</i>	<i>Key Holder Group</i>
			<i>P</i>	<i>Police</i>

No Active Alarm Notes

Transmitter Details

Transmitter No. 1: Dahua		Receiver Type: Dahua	
Signalling ID: 904:020722	Enabled on 23/03/2026	Connected on 23/03/2026	
Network Address: 194.32.68.213	User: emcs	Last Signalled on 23/03/2026	
Net Address 2: N/A		Panel Type: Standard Monitoring	
Password: C0mptonWyny@tes26!	SW Version: N/A	Model Short Code: N/A	
Polling Mode: Land line Only	Landlne Poll Interval (Radio Up): 1200 secs		
Polling Direction: Outward			

Transmitter Programming**Transmitter No. 1: Dahua****Receiver Type: Dahua****Analysis Service: Actuate****Device Type: Camera**

Zone: 2 Main Drive
 Zone: 3 Car Park
 Zone: 4 North Perimeter
 Zone: 5 East Perimeter
 Zone: 6 South East Corner
 Zone: 7 South East Perimeter
 Zone: 8 South West Perimeter
 Zone: 9 West Perimeter
 Zone: 12 Stables Track
 Zone: 14 Stable Courtyard
 Zone: 16 Machinery Barn Int
 Zone: 18 Elizabeth Walk

Device Type: Zone/Input*Activation Event**Restore Event*

Zone: 2	2	VSS Picture received	
Zone: 3	3	VSS Picture received	
Zone: 4	4	VSS Picture received	
Zone: 5	5	VSS Picture received	
Zone: 6	6	VSS Picture received	
Zone: 7	7	VSS Picture received	
Zone: 8	8	VSS Picture received	
Zone: 9	9	VSS Picture received	
Zone: 12	12	VSS Picture received	
Zone: 14	14	VSS Picture received	
Zone: 16	16	VSS Picture received	
Zone: 18	18	VSS Picture received	

Device Type: Zone/Input*Activation Event**Restore Event*

Zone: 1	1	VSS Picture received	
Zone: 10	10	VSS Picture received	
Zone: 11	11	VSS Picture received	
Zone: 13	13	VSS Picture received	
Zone: 15	15	VSS Picture received	
Zone: 17	17	VSS Picture received	
Zone: 19	19	VSS Picture received	
Zone: 20	20	VSS Picture received	
Zone: 21	21	VSS Picture received	
Zone: 22	22	VSS Picture received	
Zone: 23	23	VSS Picture received	
Zone: 24	24	VSS Picture received	
Zone: 25	25	VSS Picture received	
Zone: 26	26	VSS Picture received	
Zone: 27	27	VSS Picture received	
Zone: 28	28	VSS Picture received	
Zone: 29	29	VSS Picture received	
Zone: 30	30	VSS Picture received	
Zone: 31	31	VSS Picture received	
Zone: 32	32	VSS Picture received	
Zone: 2142	Commissioning Complete	Commisioning Complete	
Zone: 2145	Scheduling Amendment	Scheduling Amendment	
Zone: 2146	Masking Review	Masking Review	
Zone: 2159	Footage issues	Single Frame Alarms	
Zone: 2162	Trial Passed	VSS Trial Passed	
Zone: 2163	Trial Failed	VSS Trial Failed	
Zone: 5000	VSS Maint/Walk Test Completed	VSS Maint/Walk Test Completed	
Zone: 7777		Camera Connection Issue	Restore

